Revised 08/05

CORRES. CONTROL INCOMING LTR NO.

00417 RF05

DUE DATE

RECEIVED

2005 AUG 18 A 7 34 Depa

Department of Energy

COMRESPONDENCE CONTROL

ROCKY FLATS PROJECT OFFICE
12101 AIRPORT WAY, UNIT A
BROOMFIELD, COLORADO 80021-2583

AUG 1 1 2005

05-DOE-00515

DIST.	LTR	ENC
BERARDINI, J.H.	X	k
BOGNAR, E.S.	X	X
BROOKS, L.	X	X
CARPENTER, M.	X	X
CROCKETT, G. A.	X	X
DECK, C. A.	x	×
DEGENHART, K. R.	X	X
FERRERA, D. W.	X	X
GIACOMINI, J. J.		
GILPIN, H.		
LINDSAY, D. C.	X	X
LONG, J. W.		
NESTA, S.	\mathbf{x}	X
SHELTON, D. C.	X	X
TUOR, N. R.	X	X
WARD, D.	Ι.Χ	X
WIEMELT, K.	LX.	\mathbf{X}
ZAHM, C.	X	X
Heber J	X	LX
•		L.,
ButhrayM	$\perp x$	3
		<u> </u>
	<u> </u>	-

Mr. Carl Spreng
RFCA Coordinator
Colorado Department of Public Health and Environment
4300 Cherry Creek Drive South
Denver, CO 80222-1530

Dear Mr. Spreng:

Please find enclosed completed Rocky Flats Cleanup Agreement (RFCA) Type 1 building disposition Closeout Report provided for your information for Buildings 331, cargo storage building, DWF-073-05 dated July 28, 2005. This report is being submitted in accordance with the RFCA for your review and comment.

Questions can be directed to Gary Morgan, RFPO, at (303) 966-6003.

Sincerely,

John J. Rampe, Director

RFPO Closure Project/Management

Enclosure

cc w/o Encl:

S. Nesta, K-H RISS Env

J. Heber, K-H RISS D&D

K. Wiemelt, K-H RISS D&D

cc w/Encl:

D. Kruchek, CDPHE

M. Aguilar, USEPA

D. Abelson, RFCLOG

K. Korkia, RFCAB

Administrative Record

Ref. Ltr. #

COR, CONTROL ADMIN, RECORD

05BF00730

Reviewed for Addresse

DOE ORDER #

5400.1

DECEIVED 18203

ADMIN RECORD



RECEIVED



255 AS -8 P 3 W

July 28, 2005

05-RF-00730

Gary Morgan, Director Project Support DOE, RFPO

TRANSMITTAL OF CLOSE OUT REPORT FOR CARGO STORAGE, BUILDING 331 -- DWF-073-05

Attached is the Closeout Report for the Type 1 facility Cargo Storage, Building 331. Please note that a copy of the report has been submitted to the CERCLA AR by the Kaiser-Hill RISS project.

Please contact Steve Nesta x6386 with questions or concerns.

Deni W. Jam

Dennis W. Ferrera Vice President and Project Manager Remediation, Industrial D&D, and Site Services

Attachment: As Stated

SMN:jlh

Orig. and 1 cc - Gary Morgan

CC:

John Rampe

Type 1Facility Closeout Report

Section A. Facility Data		
	DIC .	•
	argo Storage, B331	
· · · · · —	ISS	
	1/2005	
Additional Information:		
(Must include information on envir	ronmental releases and conditions & site at turnover to Environmental Restoration)	
Section B. Final Characteria Reconnaissance Level Characteria	terization Report Type 1 Concurrence-Steven Gunderson to Richard DiSalvo,	
(concurrence received)	May 29,2003	
In-process Characterization	NA	
Pre-Demolition Survey Repor		
Post-Demolition Survey Repo	ort (asnecessary) NA	
Section C. Waste Data (com Sanitary Disposal	nplete categories as appropriate)	
Disposal Site:	BFI Foothills	,
Waste Volume (yd ³):	2	
Waste Weight (tons):	1	• .
Additional Information:	D diti debris fi "1 f" covering f two cargos.	
Hazardous Disposal Disposal Site:	NA	
Waste Volume (yd³):		
Additional Information:		
TSCA Waste Disposal Disposal Site:	NA	
Waste Volume (yd³): Additional Information:		
Asbestos Waste Disposal Disposal Site:	NA	
Waste Volume (yd³): Additional Information:		
Low-Level Waste Disposal Disposal Site:	NA.	
Waste Volume (yd³):		
Additional Information:		
Low-Level Mixed Waste Disp	nosal NA	
Disposal Site:		•
Waste Volume (yd³):		
Additional Information:		
Recycled Material Recycle Facility:	NA	
Waste Volume (yd³):	A north the to the court	A.ST C
Additional Information:		到到们
Property Disposition	Secretary Control of the Control of	<u>V</u>
Receiver Locations (major #10	ens only):	ma III
Additional Information:	STATE OF THE PROPERTY OF THE P	
		managed (I
Section D. Approvals	SM/20105	
Kaiser-Hill Project Manager	Norma/Signature Date	ar estima en emperativo e consect

Instructions for Completion of Type 1 Facility Closeout Report

331C was an approximately 800 square foot structure placed into service in 1975. The structure was constructed of two cargo containers placed about 20 feet apart and a roof connecting the two containers. The cargos and the area between them were used to store grounds-keeping equipment and supplies such as lawn tractors, weed-whackers, hand tools, and other supplies and equipment.

Only the roof of the structure was demolished and sent off-site for disposal as sanitary waste. The cargo containers were sent to PU&D.

331C had drop-down electrical service, which was removed prior to removal of the cargos.

4

